<u>List of Reference Numbers</u>

- 1. Safety ski binding
- 2. Runner device
- 3. Ski
- 4. Toe binding
- 5. Heel binding
- 6. Circuit
- 7. Display device
- 8. Sensor system
- 9. Adjusting screw
- 10. Release mechanism
- 11. Adjusting screw
- 12. Release mechanism
- 13. Evaluation device
- 14. Evaluation device
- 15. Sensor
- 16. Sensor
- 17. Line connection
- 18. Line connection
- 19. Transmitter and/or receiver device
- 20. Transmitter and/or receiver device
- 21. Power supply system
- 22. Power supply system

- 49 -

25.	Display
26.	Sensor
27.	Slip-on spring system
28.	Thrust bearing
29.	Helical spring
30.	Longitudinal guide
31.	Adjusting screw
32.	Line connection
33.	Sensor
34.	Clamping jaw
35.	Line connection
36.	Electronic unit
37.	Wrist-top computer
38.	Interface
39.	Screw nut
40.	Thrust bearing
41.	Helical spring
42.	Piston
43.	Hall-effect sensor
44.	Hall-effect sensor
45.	Ring magnet
46.	Collar

23.

24.

Housing

Housing

47.	Sensor signal
48.	Sensor signal
49.	Phase shift
50.	Counter
51.	Pulse
52.	Memory system
53.	Numerical value
54.	Motion sensor
55.	Magnetic field sensor
56.	GMR sensor
57.	Metal part
58.	Permanent magnet
59.	Distance
60.	Reference point
61.	Measurement range
62.	Measurement range
63.	Hall-effect sensor
64.	Hall-effect sensor
65.	Detection object
66.	Detection object
67.	Permanent magnet

Permanent magnet

68.